

Steel S. S. "Star of New Zealand"
built at Belfast by Messrs Workman, Clark & Co.
Belfast Report 4475

It is submitted the Surveyor's attention should be directed to the depths from top of floors to main and upper deck beams as stated in his report. The dimensions appear to have been taken from the bottom of the floors instead of the top, and he should be requested to state whether this is the case.

He should also be requested to state whether the thickness of the face plate to the hold stringer as fitted in the ship viz "9 20" is correctly stated in his report in view of the approved thickness being $13/20$ ths.

As to Belfast

27/3/95

W. J. C. A. J.
27/3/95



Lloyd's Register
Foundation

BEL 64-0201