

No. of Feed pumps 2Diameter of ditto 4 1/2Stroke 24

Can one be overhauled

"
S. S. Langton Grange"
"

It is submitted that before dealing with this case the Surveyor should be informed that the approved tracing of the boilers does not appear to have come to hand & he should be requested to state whether "forced draught" is applied to the main boilers, as there is no mention of it on his Report.

W. H. S.
22.5.96
Hotel 23/5/96

BEL66-0161

Lloyd's Register
Foundation

Description of Boilers

three single-ended

Working Pressure 180 lbs Tested by

No. of Boilers

boilers be overhauled separately

Area of fire grate in each boiler

56 1/2 sq ft

No. and