

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 575198 When handed in at Local Office 6 MAY 98 Port of LIVERPOOL
 No. in Reg. Book 35 Survey held at Liverpool Date, First Survey 12th April 1898 Last Survey 29th April 1898
 on the Wood, Iron or Steel S.S. "Monmouth" Master No. of Vessel 5
 TONNAGE:—
 GROSS 7950 Built at Belfast By whom Harland & Wolff When 1898
 UNDER DR. V Owners African S. S. Co. Port belonging to Liverpool
 NET Owners' Address (If not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Afloat Name of Dock Langton Destined Voyage New Orleans
 WB=Cell DB or DBa feet; uE&B feet; I feet; T feet; total capacity tons. FPT tons; APT tons; MT tons; feet tons.

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. Port

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and details being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawser is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE, FOR This vessel came here from Belfast for the purpose of having her engines and boilers placed on board, while entering the dock at this port she struck the Pier Head, and indentured two plates on the port bow.

From a letter received from the Society's Surveyor at Belfast it appears that the hull of the vessel was completed before she left with exception of permanently closing in the engine and boiler hatchways.

How Done—The engine and boiler hatchway permanently closed and made efficient, and the two indentured plates on the port bow taken off, fairied and refitted.

IMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed	✓							
Removed and Fair'd on Repaired	✓	✓	✓	✓	✓	✓	✓	
Fair'd or Repaired in place	✓							

PRESENT CONDITION OF THE	Stringers.	Engine Room Skylights.	Boats.
Decks	Inner Bottom Plating.	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.
Walking of Decks	State if Tanks now tested.	Scuppers.	Condition, how ascertained
Portways	Bulkheads	Cargo Hatchways.	(State if wedges removed)
Timings	Ceiling	Hatches	Sails
Fastenings	Cement or Asphalt. (State which.)	Planking of Wood Vessels	Equipment letter
Side Plating	Rudder	Treenails ditto	Anchors, No. of
Walking of ditto	Windlass	Breasthooks & Stemson ditto	Cables (State if now ranged)
etc.	Have Pumps now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	" length (on board) size
aststocks & Crutches	Have Sluice Valves now been examined and found efficient?	Tilthers of Frame at openings ditto	" Rule length (per Table 22) size
nsoms	Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places ditto	Hawsers & Warps
erse Frames	Denting. Plates under Sounding Pipes.	Stringers, Clamps & Shelves ditto	Standing & Running Rigging
ons		Salting (State if examined.) ditto	
		Copper, or T.M. (State if on Felt.) ditto	
		When put on, Month Year	

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—".....to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.98," or "to remain as classed and to have record of survey, 1.98, and the notations of 'No. 1-98 and ptND98, &c.'"

The above mentioned repairs are reported for the Committee's information

Fee (if chargeable) per Scale II., Sec. 37 £	:	Fees applied for,
by Fee (per Section 38) £	:	18
al Damage or Repair Fee (if any) (per Sec. 3d) £	:	Received by me,
illing Expenses (if chargeable) £	:	18
Surveyor's Fee (if any) £	:	

Committee's Minute LIVERPOOL. - 6 MAY 98

Tracter assigned Transmit to London.

R. Williams
Surveyor to Lloyd's Register of British & Foreign Shipping.

TUES. 10 MAY 1898

© 2019



BE668-0056