

FRI JUL 1900

Pelfast

July 4th 1900


James Simpson

Messrs Harland Wolff Ltd.

Survey the New Steel River Steamer
"Dormion", in order to ascertain the
extent of damage stated to have been
sustained while being launched on
the 2nd floor.

On examining the vessel while lying
alongside the Alexandria Wharf on the
port on the 2nd July found in the fore
hold on the Port side, directly under the
fore hatch, the cement bottom in fore space
fore floor bent vertically just outside the
center girder angle, and a few rivets blown
in the double bottom angles and center
floor plate keelson.

Recommended that the vessel
placed in dry dock as early as convenient
for further examination; that the rivets
the rivets in the neighborhood of



inside and outside be carefully listed and
 renewed when necessary, and the staves and
 butts of plating, examined and recanted,
 when stained; that the bent staves be joined
 in place. The canvas renewed when broken
 or cut out for sewing, and the view and
 distended work presented so as to place the
 vessel in as good condition as she was in
 before the damage occurred.

The £2.2.0

Less 10/-
£1.10.0

James Thompson

Pd. 6/7/80
 AP 17-7-00



© 2019

Lloyd's Register

Belton 0155 (210)

RECEIVED OF SHREVE
JAN 10 1809

which are better & carefully letter and
renewed when necessary. And the letters are
lots of blank specimens and occasional
other specimens, that the first place to find
in place. The common specimen when better
is not for money, and the new and
disturbed most probably as a place the
great in our own country as the new in
before the change comes.

The 1809-10 in my family group in
1809-10 in my family group in
1809-10 in my family group in

PAID 10/10/1809
10/10/1809



© 2019

Lloyd's Register
Foundation