

1.

Sent to Chief Surveyors 15. 9. 00

VESSEL'S NAME 1st S.S. "Seoniam"

Received from Chief Surveyors
 Report Sur. No. 49238

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Damage

When done

Noted
 C.H. J.
 18/9/00

[Faint handwritten text, likely bleed-through from the reverse side of the page]

Dr. to Bel



© 2019

Lloyd's Register Foundation

No. of Side Stringers	20	30	12	26	1	12	10	6	10-0164
EB-FRAME, E. & P. Space, No. & spacing	26	12	26	1	12	10	6	10-0164	
EB-FRAMES, In After Body, No. and spacing	26	12	26	1	12	10	6	10-0164	
brdth. & thickness	26	12	26	1	12	10	6	10-0164	
brdth. & thickness	26	12	26	1	12	10	6	10-0164	
No. of Side Stringers	20	30	12	26	1	12	10	6	10-0164