

549

Appledore 15 July 1849

Charles Graham Esq<sup>r</sup>

Sir

In reference to  
the schooner Rose - When Mr George  
was at Newgate last Dec<sup>r</sup>, and surveying  
the said schooner it has been understood  
that she had to have two Hold Beams -  
Now the Builder informs me that the  
Owner would rather not have the Hold Beams  
and that the Committee did not require  
them

The Rose is as fair 12 years old  
except the Hold Beams which I think should  
be - say one abaft the Foremast and one  
before the Mainmast

Yours

Sir

John Mart Old And New  
James Power

BID73-0278

*lrb midland*



© 2019  
Lloyd's Register  
Foundation