

Copy of Telegram

4 Feb: 80.

Lloyd's Surveyor and the Builder have together tested vessel as to actual amount of leakage.

The former reports to his Committee and as a subordinate considers any opinion must be obtained from them.

3.45 P. M. yesterday water in sounding well (15 feet abtft mainmast)  $13\frac{1}{4}$  inches; forward (8 feet before foremast)  $7\frac{1}{4}$  inches -

At 9.45. A. M. today  $23\frac{3}{4}$  and  $13\frac{3}{4}$  inches respectively.



© 2020

Lloyd's Register  
Foundation