

Received by Chief Surveyor

7-6-98

Received from Chief Surveyor

2

VESSEL'S NAME

Irish Curdydice

Report

Apl

No.

2625

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ature of Survey

S.S. No. *3*

The S.S. No. *3*

has now been held, and the following repairs

done (due to wear *stern*):— 16 fore-castle side plates renewed, stern plating in way of carved work, and one shell plate doubled, decks repaired & recaulked, a number of shell frame rivets, the running rigging and a breasthook renewed, cement repaired, and a number of minor repairs to spars & rigging done.

The shell plating has been drilled. See sketch attached, and the Surveyor's letter dated 3rd June.

It is submitted the vessel is worthy to remain classed

100A1

with record of Survey

5.98

and notation of S.S. *Apl*

2nd No. 3-5.98 as recommended.

100A1

5.98 Apl.

S.S. Apl 2nd No. 3-5.98



© 2019

Lash
Hoy's Register

7/6/98

BID71-0186