

Received by Chief Surveyor 12-12-99

Received from Chief Surveyor

VESSEL'S NAME Sm Bk "Broughlon" Report Apl No. 2663

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

PS NO 2

It is submitted that before this case receives the consideration of the committee, the sketch of drillings should be ^{returned} forwarded to the surveyor and his attention should be called to the thickness noted thereon in pencil which are the original thicknesses as per first entry report.

In view of the diminution of thickness reported particularly on midship portion of strake No 6, he should be requested to state whether the plating was drilled in locally wasted places, or if the thicknesses reported represent the general condition of the plating.

With regard to the request contained in Mr. Yeomans letter regarding date of classification certificate, the surveyor should be requested to inform Mr. Yeoman that the request cannot be acceded to.

12-12-99

G.H.B.



© 2019

Dr. to Apl. 12-12-99

Lloyd's Register
Foundation
BID77-0260