

31077-0288

floated off on the 7th of June 1900 and
 proceeded to ~~off~~ ^{off} Heligoland where the
 ship could be partially salvaged except
 the bottom as that was lying in the mud.
 I could see no indication of straining
 either in deck or the sides
 Loaded the clay taken out when she
 proceeded to sea on the 8th June 1900

Recommend that the vessel be placed
 either in the dock or Quayside for the
 further examination of the bottom.
 The propeller removed and fresh
 fitted as it is not in a satisfactory
 state the nut on the aft side is slack
 and the propeller not properly tight on the
 shaft. ~~all~~ ^{the} loosened while she
 on the ground with working in the sand
 and that 3 new warps supplied of
 60 fathoms each of 5" Brandell's

Fee 2.2.0
 Expenses 5.10
 £ 2.7.10

G. Westcott
 Lloyd's Surveyor
 Heligoland



© 2019

 Lloyd's Register
 Foundation

B1077-0288 (2/4)