

Received by Chief Ship Surveyor 14. 7. 00

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME S. S. S. "Fremington" Report Apl. No. 2680

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.

Nature of Survey Repairs.


The Appledore Surveyor reports that on account of leakage on starboard side of fore hold through the riveting of the rubbing piece, the rubbing piece has been reriveted and some rivets in the plating renewed.

It is submitted the vessel is worthy to remain as classed without fresh record of survey, as recommended.

J. H. T.  
14/7/00

C. J. P.

The Appledore Surveyor should be informed that the copy of damage survey report sent by him is incomplete, he has only sent one sheet; he should be requested to forward the remainder.



Lloyd's Register  
Foundation

J. H. T.

BID 77-0292