

~~ENCLOSURES.~~

FRI, 13 JUL 1900

Lloyd's Register of British & Foreign Shipping  
Liverpool, July 12<sup>th</sup> 1900

• Telegraphic Address:  
"REGISTER, LIVERPOOL."

R. Williamson Esq.  
Sir.

With reference to the Secretary's letter of the 11<sup>th</sup> inst. regarding the S/s "Fremington" enclosing the Appledore Surveyor's Report, I beg to inform you that this vessel was repaired under my survey in June when one plate was renewed and two faired and replaced on Starboard side of forehold, and that these repairs were found on completion to be sound and satisfactory.

The started and leaking rivets referred to in the Appledore Report 12680 are probably due to the vessel touching the dock wall when leaving Liverpool.

BID 71-0294 (1/2)




Damage from this cause is of common occurrence at this port owing to the difficulty in entering and leaving many of the docks, and has lead to the fitting of rubbing plates and chafing bars-especially on the starboard side - on many coasting vessels trading here.

I am, Sir,

Your obedient Servant.

C. A. G. Nash



© 2019

Lloyd's Register  
Foundation

B1D71-0294(2/2)