

1.

Sent to Chief Surveyors

2.7.00

Received from Chief Surveyors

VESSEL'S NAME

Lb Elliott

Report

Apl drilling up

For the CHIEF SHIP SURVEYOR ~~AND CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due

It is submitted that before the results of the drillings receive the consideration of the Committee, the Appledore Surveyor should be requested to state whether the plating has been drilled in locally wasted places, or whether the thickness^{ess} ascertained by the drillings represent the general condition of the plating. It should be pointed out to him that where the plating of the poop sides has been drilled, under the side lights, considerable diminution appears to have taken place, and he should state what is proposed to be done with reference thereto. He should also be informed that a letter advising the forwarding of the sketch of drillings for submission to the Committee should have accompanied the same.

Lr. to Apl. 3/7/00.



C. R. J.
© 20/7/00

Lloyd's Register
Foundation

BID 77-0305