

1.

Sent to Chief Surveyors 5 JUL 1900

Received from Chief Surveyors

VESSEL'S NAME *Sok Elliott*

Report No.

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey *2nd. S. S. No. 3*

When due

This vessel is undergoing the 2nd S.S.No.3 at Appledore and the Surveyor has forwarded a sketch of the drillings. He states in reply to enquiry that the plating has been drilled in locally wasted places, and that the general thickness is satisfactory. With regard to the diminution which appears to have taken place under the side lights, he states that these parts will now be doubled to compensate for the wasting.

It is submitted under these circumstances that the plating may be considered satisfactory, subject to the parts under the side lights being doubled as proposed and to the satisfaction of the Surveyor.

J.S.

C.R.J.
5/7/00

FRI. 6 JUL 1900

Approved subject

K.C.

L.H.K.
Apr 6/7/00



© 2019

Lloyd's Register
Foundation

BID77-0308