

SHIPBUILDING YARD & GRIDIRON,  
 CLEAVEHOUSES.

WESTACOTT,  
 YACHT BUILDER,  
 BIDEFORD.

Bideford, <sup>nd</sup> Feb 22 1905

Lloyds Committee  
 Gentlemen

LLOYDS REGISTER  
 LONDON.

REC'D 23 FEB 1905

ANS'D 73<sup>th</sup> to Apple-dore

Re "Elwood"

I was rather disappointed with your  
 reply as to the Class suggested for the  
 Schooner "Elwood" May I ask you to please  
 reconsider the matter as two thirds of  
 5 years rather more than 3 years hoping you  
 will see your way to give her 4 years  
 I should suggest that Mr Westcott your Surveyor  
 should take off the Materials now in ship  
 as she has had new Beams of Pitch Pine  
 and P. Pine Shelves & ceiling renewed. Main  
 and Rudder & Oak also Windlass and  
 new deck 2 years since hoping you will  
 see your way of doing this

I remain

Dear Sirs

Yours faithfully  
 John Westcott

© 2019

Lloyd's Register  
 Foundation

BID77-0390



Referred to the Chief Ship Surveyor.

  
23 FEB. 1905

Wood Schooner "Elwood"

Also for Mr. S. A. Hill to note

It is submitted the Appellate Surveyor should be requested to make an examination of the schooner "Elwood" now under repair at Mr. Westcott's Yard, Wileford, and ascertain and report <sup>fully and in detail</sup> upon the description, quality and distribution of the wood material now existing in the vessel; Mess Westcott having applied for an improvement upon the term of years originally assigned to the vessel in order to increase the term for which she would be eligible under 2<sup>nd</sup> Survey for R. M. S.

Dr. 22.2.05

 23/2/05

© 2019

Lloyd's Register  
Foundation