

SHIPBUILDING YARD & GRIDIRON,  
CLEAVEHOUSES,N WESTACOTT,  
D' YACHT BUILDER,  
BIDEFORD.Bideford, Febry 18<sup>th</sup> 1905Committee of Lloyds  
GentlemenLLOYDS REGISTER  
LONDON.

REC'D 20 FEB 1905

ANS'D 20/2/05

I have the Schooner "Elwood" here at my Yard  
under a very heavy repair doubling her with  
T. Pine plank. Elm bottom and 5" bilges well  
stepped all the fastenings renewed through the  
plank such as Iron Riders. Bidge Channel. Shelf  
and Limber bolts renewed. very recently had new  
deck. What I cannot understand how the  
set had so short a Class the first Building  
should have thought for the Materials in the Ship  
would have at least 8 years & 1 being salted  
all you please let me know the most you can give  
in the Red Letter. Your Surveyor Mr. Westcott  
will give you all the information you may require  
he has been Surveying her

Yours Obediently  
J. Westcott

© 2019

Lloyd's Register  
Foundation

B1077-0393



*Referred to the Chief Ship Surveyor.*

*as*

20 FEB. 1905

*Also for Mr. S. A. Hill to note.*



© 2019

Lloyd's Register  
Foundation