

Steam Drifter "Providence" built at Appledore by Messrs R. Cook & Co  
but engines made by Mr Wm. Burnell not outpiped during construction.  
The Surveyor states that the engines have not been examined.

It is submitted that the Master be informed  
that the vessel will not be Classed until the  
various parts of the engines & all the fittings  
have been thoroughly examined by a Surveyor  
of this Society & tried under steam, & the  
safety valves adjusted to a working pressure  
in accordance with the Rules, & he should be  
requested to state definitely when & where  
this will be done.

In the case of any other vessel to be built <sup>for</sup> by him  
this Society's classification cannot be assigned unless both hull  
and machinery are built under survey & the foregoing complied with.

12: 25/10/07

24/10/07

C.B.

23.10.07

BID 77-0542