


mitted the Appledore Surveyor should be informed  
his reply of 17 Oct is considered unsatisfactory, it  
evident therefore that he has not complied with  
instructed instructions which were sent to him.

The surveyor should be requested to forward a  
of all the vessels building under his survey together  
request forms, duly filled in and signed, for such  
vessel as request forms have not already been  
plied: He should also state where the masts <sup>if any</sup> are being built  
He should be requested to be more careful in  
giving with the instructions to exclusive surveyors  
nature and should bear in mind that the hull of a  
cannot be classed  
the machinery is  
classed.

  
18/10/07  
18.10.07

© 2019 AB

Lloyd's Register  
Foundation

B1077-0549