

We have looked through the correspondence,
likewise the Report for ² Entry, and are of opinion
that as the case at present stands, she cannot
be recommended for higher than 10 A, with
one year to be added for Copper Bolting when
the Hulls of the Cant Timbers are Bolted
through the Outside planking, with Copper or
Yellow Metal.

June 29 JH IHR



© 2019

Lloyd's Register
Foundation

BR580-195