

Steel Screw Lug No. 59.

Built at Gloucester by Summers & Scott.

Bristol Report No. 5555, 12/12/92.

It is submitted that before this case receives the consideration of the Committee the Report should be returned to the Surveyor, and his attention should be directed to the equipment which appears to have been supplied in accordance with the Secretary's letter of approval dated 18<sup>th</sup> Sept. /92, ~~and also being the case~~ he should be asked to state why he has not recommended the figure 1 for equipment.

in W. H. S.  
22/12/92

G. S.

C. H. J.  
22/12/92



© 2013  
Lloyd's Register  
Foundation

BR582-0138