

Steel 4 Mast BK "PAUL"

(ex Willy Rickmers)

Built 1895-8mo.

Bone
679

Please return to FE

Plan bag



© 2020

Lloyd's Register
Foundation

Rules, and I shall be obliged if you will kindly state for the information of the Committee when and at what port it will best suit your convenience to comply with this requirement.

For yor information I beg to enclose a list of the ports at which Surveyors to this Society are stationed.

I am, Dear Sirs,

Yours faithfully,

A. Scott

Secretary.

Extract from the Rules referred to above:-

The stern shaft is to be examined annually and drawn at intervals of not more than three years in the cases of shafts fitted with continuous liners, and of not more than two years in the cases of other shafts.