

Received by Chief Surveyor 14. 3. 99

Received from Chief Surveyor _____

VESSEL'S NAME Sgt. S. S. "Fred"

Report Brw No. 866

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey _____

First entry

It is submitted that before this case receives the consideration of the Committee, the Glasgow Surveyors should be requested to see that the openings in the deck over the engines and boilers are efficiently covered, and to forward a report on completion of the work to their satisfaction, for the information of the Committee.

M. L. Barron
14/3/99.

C. H. J.
14/3/99



© 2021

Lloyd's Register
Foundation

BRW46-0128

Angles on Upper Edge

Average space

21

21

Bridge Deck Stringer Plate, brdth & thickness

„ Angle on ditto

2 1/2 x 2