

Reference

# Lloyds Register of British and Foreign Shipping.

LLOYDS' REGISTER  
LONDON.

RECR 12 NOV. 92

AN8R

Back Chambers, Barry.

11<sup>th</sup> November

1892.

S. S. Clive. Report (f.e.) No. 209.

Sir.

As requested I respectfully beg to state that the reason why no bilge infection has been fitted to this vessel's Machinery, "is that the builders (with the Owner's consent) considered, that as it was most probable that the vessel would never ply outside the limits of Barry Dock the fitting of the bilge infection might be dispensed with. They are however quite willing to fit a bilge infection should at any time the vessel have to ply outside of the Barry Dock. I may state that upon making enquiries I find that in this class of vessel it is most unusual to fit bilge infections.


The Secretary  
London.

I am Sir  
Your obedient Servant  
John B. Taylor.



© 2021  
Lloyd's Register  
Foundation





Lloyd's Register  
Foundation

The Rules require  
 as the extra pumping  
 the cost of the  
 "A large section, in a large  
 It is submitted one or other  
 may be required until the work is finished.  
 N.A. 14. 11. 92  
 12/11/92  
 © 2021  
 Lloyd's Register  
 Foundation