

It is submitted the Barry Surveyors should be asked if there were any other holes in the tunnel plating of the S.S. "Dumail" in addition to those included in the damage and reported by them as such.

They should also be asked to state whether ~~any~~ of the deck plates renewed on account of damage were sufficiently wasted to render renewal necessary on that account if they had not been damaged.

B. 11/6/08



© 2021

Lloyd's Register
Foundation