

2 Enc

Cadiz 5 January 1888

LLOYD'S REGISTER,  
LONDON.

REC'D 11 JAN. 88

ANS'D

B Weymouth Esq  
Dear Sir

Enclosed you will find the accounts of all the Surveys I have had since April '87 to the 31 Dec<sup>r</sup> having been in England the rest of the year Building a large Steamer.

You will also see I have to announce the loss of two Spanish Steamer viz The Alegria and the Ana Haynes of this port in having through the bad weather that has prevailed here these last two weeks by having snapped the chains the "Alegria" by having run on some rocks on the bar at Port St Mary's the other "Ana Haynes" being Wood & Paddle has drifted onto the sands of the Caibazuela and breaking as fast as possible.

Ref No 20  
reg No 5

With regard to the Steamer William Haynes I have had sixteen holes bored in her in different parts where I thought was necessary such as close to the Bulkheads as possible in the bottom and sides and I find that the most the plate was reduced from 1 to 1/2 milimetre and seeing that her original plates being thicker than required by the rules of the Society please to let me have the certificates if possible I remain your obt<sup>t</sup> servant.

M Lth Nov 25 787

Lloyd's Register  
Foundation

To Mr. Invern, Mr. Keir and  
Mr. Scott of rate

Handed to Mr. Keir  
24.1.88

B. J. P.

11/88

Mr Lockman should give a  
detailed report <sup>preliminary</sup> showing in what  
respects the Special Fisher No 3  
have been complied with, and state  
the various thicknesses of the  
several parts measured by him.

To Mr. Invern  
24.1.88.

J. D. L.  
23/1/88



© 2021

Lloyd's Register  
Foundation