

1

Sent to Chief Surveyors 2.11.10.

Received from Chief Surveyors

VESSEL'S NAME SS. British Queen Report Sub. No. 2937

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Surcey windlass When due

Noted

M

2.11.10

*for w-sa still to note
advise Lon. sur. in
due course*

2.11.10



© 2019

Ed Dungeles
Lloyd's Register
Foundation

DU399-0052