

Chief Ship Surveyor 18.9.11.

Received from Chief Ship Surveyor \_\_\_\_\_

NAME SS "Pray Head" Rpt. Sub. No. 3081

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. —Extract from Sub-Committee's Report, 24/5/92.

Survey COMPLETION OF 2<sup>nd</sup> S.S. No. 1

The 2<sup>nd</sup> S.S. No. 1 partly held at Middlesbrough Belfast

now completed, and the following repairs done due to wear and tear:-

*Hoops in No 2 ballast tank in way of Donkey boiler repaired by doublings: wash plate in after peak repaired & minor repairs.*

It is submitted the vessel is worthy to remain as classed, with record of Survey 9.11 Sub and notation of S.S. Mdb No. 1-11 as recommended.

*100 A. 1  
9.11 Sub.  
Mdb. No. 1-11.*

*W.A.W.  
18/9/11*

