

Steel Schooner "OLWEN".

It is submitted the Dublin Surveyor should be informed that from enquiries made of Messrs. Mortimer & Bacon, it appears that the motor in question has not been built under special survey.

If it is desired to have the motor certificated, it would first be necessary for full particulars of the motor and its shafting to be furnished, so that the matter might be considered. If it is not desired to have the motor certificated the Dublin Surveyor should still see that the motor is efficiently secured to the seating, that the sea connections, stern tube, screw shaft, are properly fitted, and that reasonable and proper precautions are taken to prevent danger from fire.

L.M. - 30/6/14

J.M.

A.R.R.

30.6.14.



© 2019

Lloyd's Register
Foundation

DUB99-02472