

(Received at London Office)

RECEIVED
OCT. 83

Tests of 1 Steel plate manufactured by Messrs. N. Beardmore & Co. of Parkhead
for Boiler No. - to be constructed by Messrs. Gourlay Bros. of Dundee.
for the S.S. "Plover"

Date first visit 1st Oct. last visit 8th Oct. No. of visits Constant-attendance

The _____ specified in the accompanying copy of Advice Notes were rolled from _____ charges. The tensile test has been applied to one samples as set forth below, and the temper and bending tests applied to piece cut off this Plate with satisfactory results.

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

Expenses £ : :

£ : :

To be paid by

[T. & S.—10,000—6/3/38—Trans. Ink.]

DUN 113-0134