

No. 8558

(Received at London Office,

TESTS OF BOILER STEEL.

Tests of 1 Steel plate manufactured by *The Steel Co. of Scotland* of *Glocharin* for Boiler No. *—* to be constructed by *Wm. Gairdner & Co.* of *Glasgow* for *the S.S. "Plover"*

Date first visit *24/8/88* last visit *6/9/88* No. of visits *—*

The *—* specified in the accompanying copy of Advice Notes were rolled from *—* charges. The tensile test has been applied to *1* samples as set forth below, and the temper and bending tests *satisfactory*

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge.	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch.		
					Ins.	Ins.	Ins.	Tons.	Tons.	%	
1	<i>End. pl.</i>	<i>1/16 B-275</i>		<i>9111</i>	<i>.73</i>	<i>1.3</i>	<i>.949</i>	<i>28.1</i>	<i>29.6</i>	<i>24</i>	

Fee £ : :
 Expenses £ : :
 £ : : To be paid by

J. Roberts
 Surveyor, Lloyd's Register,
 Glasgow
6/9/88