



No. 8643

TESTS OF BOILER STEEL.

Tests of 2 Steel plate manufactured by James Hardman of Parthead  
 for Boiler No. - to be constructed by Gourley & Co. of Sunder  
 for S.S. Flower

Date first visit 6/9/88 last visit 17/9/88 No. of visits -

The ✓ specified in the accompanying copy of Advice Notes were rolled from  
✓ charges. The tensile test has been applied to 1 samples as set forth below,  
 and the temper and bending tests applied to each plate with  
good results.

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins. %	Remarks.
					Thickn.	Brth.	Area.	Total	Sq. Inch		
					Ins.	Ins.	Ins.	Tons.	Tons.		
	126ia x 1/4	V119		952	.74	1.54	.991	27.9	28.1	22.0	previously reported 8/9/88

*Alc*  
18.9.88

Fee ..... £ : :  
 Expenses £ : :  
 £ : :

To be paid by



Surveyor, Lloyd's Register.

*Harford*  
17/9/88