

REPORT of SURVEY for REPAIRS.

No. 266 Survey held at Glasgow Date 15th October 1849
 on the Ship "Gemindar" Master George Poole
 Tonnage 587 Built at Port Glasgow When built 1841
 By whom built 707 Owners King & Co.
 Port belonging to Port Glasgow Destined Voyage Port Philip and Sydney
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 2472 Port Port Glasgow Classed 12 A. 1

REPAIRS At Present the Breasthook & Port & Starboard Decks taken out and Renewed with British Oak Timber being rotten.

The Mizen Mast New

In Dry Dock at Greenock to examine the Yellow Metal Sheathing which required only a few Nails

Present Condition of the

Decks <u>In Good Condition</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>2 Main & 2 Bilge do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>4 do</u>
Upper Deck Beams & Fastenings <u>Sound & Firm</u>	Timbers of the Frame <u>do</u>	Masts, Yards, &c. <u>In Good Condition</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>do</u>	Sails <u>Complete and Good</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>3 13th 1 11th 1 10th 1 9th</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>Complete and Good</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do do</u>
Wales <u>do</u>	Copper <u>2 Metal</u> When put on <u>1848</u> <u>do</u>	Standing & Running Rigging <u>do do</u>
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion, This Ship is in good Condition and fit for the safe Conveyance of Dry and Perishable Cargoes to and from all parts of the World and may continue as Classed.

The Amount of Fee.....£ 3 : " : " is received by me,

Special..... " : " : "

Certificate (if required) " : " : "

Committee's Minute 23rd Oct 1849

Character assigned 12 A. 1



© 2019

Lloyd's Register Foundation

GLS1410-0249