

REPORT of SURVEY for REPAIRS.

No. 400 Survey held at Glasgow Date 14th November 1850
 on the Brig "James" Master Angus M. Donald
 Tonnage 173 Built at Perth When built 1840
 By whom built _____ Owners Henderson
 Port belonging to Glasgow Destined Voyage Demerara
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 328 Port Glasgow Classed 5.A.1

REPAIRS Of Damage, At Present Renewed Six Bulwark Stanchions with English Oak and repaired the Rails and Bulwarks, Several Chain Plates and Bolts repaired and renewed Caulked from the Sheathing over all

Present Condition of the

Decks <u>in Good Condition</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Nice Good</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>2 Metal do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>2 do</u>
Upper Deck Beams & Fastenings <u>Sound & Firm</u>	Timbers of the Frame <u>do</u>	Masts, Yards, &c. <u>in Good Condition</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>do</u>	Sails <u>Complete and Good</u>
Planksheers <u>do</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>2 13^{lb} 1 12^{lb} 1 10^{lb} 1 8^{lb} 1 6^{lb} 1 4^{lb} 1 2^{lb}</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>Complete and Good</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do do</u>
Wales <u>do</u>	<u>Screw Gine</u> When put on <u>1850 do</u>	Standing & Running Rigging <u>do do</u>
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion, This Brig is in good Condition and fit for the safe Conveyance of Dry and Perishable Cargoes and may continue as Clased

Wm. Robertson

The Amount of Fee.....£ 1 : 0 : 0 is received by me,

Special..... " : " : "

Certificate (if required) " : " : "

Committee's Minute 19th Nov^r 1850

Character assigned As before



© 2019

Lloyd's Register Foundation

GLS140-0378