

REPORT of SURVEY for REPAIRS.

453

No. 453 Survey held at Glasgow Date 15th March 1851
 on the Brig "Clifford" Master William B Young
 Tonnage 209 Built at Nova Scotia When built 1840
 By whom built 153 Owners John Dickie & Co.
 Port belonging to Glasgow Destined Voyage Saint Thomas & Antigua
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 426 Port Glasgow Classed 4 F. 1
 S. S. = 50 = 4 Year Cont. 1 Year

REPAIRS Of Damage

Refastened the Plank sheers, Removed and Refitted the Head
 Knee with New Head Rail &c, Bowsprit lifted, examined and Caulked under
 Two new Bulwark Stations, Bulwark repaired, New Partners to the Fore and
 Main Masts and New Pumps, A piece of new Waterway across the After End
 of the Deck, Two Additional Iron Hanging Knees to the Main Hatch Deck Beam
 Several Starboard Bolts to the Deck Beam Knees and One Deck Plank renewed
 A new Fore Card.
 Caulked from the Sheathing over all

Present Condition of the

Decks <u>On Good Condition</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Winch Good</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>2 New do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>2 do</u>
Upper Deck Beams & Fastenings <u>Sound & Firm</u>	Timbers of the Frame <u>do</u>	Masts, Yards, &c. <u>Complete and Good</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>do</u>	Sails <u>do do</u>
Plank sheers <u>Good</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>3 1/2 1 1/2 1 1/2</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>Complete and Good</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do do</u>
Wales <u>do</u>	Copper <u>Iron Metal</u> When put on <u>1850</u> <u>do</u>	Standing & Running Rigging <u>do do</u>
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion, do now in good Condition and fit for the safe Conveyance of dry
and perishable Cargoes and may continue as Classed

Wm. D. Robertson

The Amount of Fee.....£ 1 : : is received by me,

Special..... 2 : 2 : :

Certificate (if required) " : " : "

Committee's Minute 25th March 1851

Character assigned A. 1

record repairs



© 2019

Lloyd's Register
Foundation

GL5140-0423