

# REPORT of SURVEY for REPAIRS.

1534

No. 1534 Survey held at Glasgow Date 14<sup>th</sup> February 1859  
 on the Barge "Crouch Brothers" Master George Crouch  
 Tonnage 341 Built at Bristol When built 1834  
 By whom built ✓ Owners Crouch Brothers  
 Port belonging to Bristol Destined Voyage Batavia & Singapore  
 If Surveyed Afloat or in Dry Dock Patent Slip

Last Survey, No. 21351 Port London Classed 12 1/2

REPAIRS Off Damage: At Present Shipped the Yellow Metal Sheathing  
 Cleaned the Bottom, Caulked from keel to gunwale and Waterways  
 Removed the Chamber Pipes and Boilers, Renewed the Lead Pipes,  
 Caulked and replaced the Gun Pipes and Boilers  
 Sheathed the Bottom with Yellow Metal over Paper and Felt

## Present Condition of the

Decks <u>Good</u>	Treenails <u>Where seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>Where seen do</u>	Pumps <u>2 Metal do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do do</u>	Boats <u>3 do</u>
Upper Deck Beams & Fastenings <u>Sound</u>	Timbers of the Frame <u>do do</u>	Masts, Yards, &c. <u>Complete &amp; do</u>
Lower Deck Beams & Fastenings <u>Sound</u>	Keelsons <u>do do</u>	Sails <u>do do</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>do do</u>	Anchors No. of <u>31 1/2 1 1/2 1 1/2</u>
Sheerstrakes <u>do</u>	Ceiling <u>do do</u>	Cables <u>Complete &amp; Good</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do do</u>
Wales <u>do</u>	Copper <u>Yellow Metal</u> When put on <u>Ship 59</u>	Standing & Running Rigging <u>do do</u>
Plank (Bottom) and Counter <u>do</u>		

## General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways done & Good

Now in good & efficient condition fit for the safe conveyance of dry and perishable cargoes to and from all parts of the world and to continue as above

The Amount of Fee.....£ 1 : - : - is received by me,

Special.....£ 4 : 4 : -

Certificate (if required) " : " : "

Committee's Minute 25<sup>th</sup> February 1859

Character assigned 12 1/2

record damaged repair



© 2019

Lloyd's Register Foundation

GLS142-0271