

1721.

REPORT of SURVEY for REPAIRS.

Rec 18/10/60

No. 1721 Survey held at Glasgow Date 9th October 1860
 on the Ship "Shorthillside" Master John Curran
 Tonnage 600 Built at Sunderland When built 1852
 By whom built _____ Owners H. L. Seligmann
 Port belonging to Glasgow Destined Voyage New York
 If Surveyed Afloat or in Dry Dock Patent Slip

Last Survey, No. 4045 Port Clyde Classed 10 A 1

REPAIRS At Present, Shipped the Yellow Metal Sheathing, Chained the
Bottom

Renewed, One Worned Bottom Plank Amidships above Bilge with
Rock Elm; Put in Five Pairs of Additional Chain Rider Hanging
Stays to Hold Beams Extending to Bilges
Put New Gale Keel
New Fore Mast and Main Mast
Caulked from Keel to Gunwales and Waterways
Sheathed the Bottom with Yellow Metal over Felt

Present Condition of the

Decks	<u>Good</u>	Treenails	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>do</u>	Breasthooks and Stenson	<u>do</u>	Pumps <u>4 in</u>	<u>do</u>
Comings	<u>do</u>	Transoms, Pointers, and Crutches	<u>do</u>	Boats <u>3</u>	<u>do</u>
Upper Deck Beams & Fastenings	<u>Sound</u>	Timbers of the Frame	<u>Where Seen, do</u>	Masts, Yards, &c.	<u>Complete & Good</u>
Lower Deck Beams & Fastenings	<u>Firm</u>	Keelsons	<u>do do</u>	Sails	<u>do do</u>
Planksheers	<u>Good</u>	Clamps and Shelves	<u>do</u>	Anchors No. of <u>3 1/2</u>	<u>1 Stem 1 Bidge</u>
Sheerstrakes	<u>do</u>	Ceiling	<u>do do</u>	Cables	<u>Complete & Good</u>
Topsides	<u>do</u>	Rudder	<u>do</u>	Hawsers and Warps	<u>do do</u>
Wales	<u>do</u>	Copper	<u>Yellow Metal</u> When put on <u>Deck 1860</u>	Standing & Running Rigging	<u>do do</u>
Plank (Bottom) and Counter	<u>do</u>				

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good

As in good and efficient condition fit for the safe conveyance of
Dry and Perishable Cargoes to and from all parts of the World and
may continue as Classed

The Amount of Fee.....£ 2 : : : is received by me,

Special..... / : / : :

Certificate (if required) : : 5 : :

Committee's Minute 19th October 1860

Character assigned 10 A 1

record repairs

Wm Robertson



© 2019
 Lloyd's Register
 Foundation
 GLS 142 - 0406