

1759

REPORT of SURVEY for REPAIRS.

No. 1759 Survey held at Dumbarton Date 8th February 1861
on the Ship Vinidad Master John Wyllie
Tonnage 485 Built at Dumbarton When built 1854
By whom built A. McMillan Esq. Owners John Kerr
Port belonging to Glasgow Destined Voyage Demerara
If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 1639 Port Glasgow Classed GA 1
2.60

REPAIRS Of Damage. Shipped the Yellow Metal Sheathing, cleaned the
Bottom; renewed the After Piece of Keel and the entire False Keel,
Additionally Bolted the Clamps to Hold Beams; repaired the Bulwarks
and Rail, Channel Boards and Chain Plates, six new Scuppers
on Main Mast, Main Topgallant Mast and Fore Topgallant Mast
new
Caulked over all, Re-sheathed the Bottom with Yellow Metal over Salt

Present Condition of the

Decks <u>On Good Condition</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>4</u> <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>3</u> <u>do</u>
Upper Deck Beams & Fastenings <u>Sound</u>	Timbers of the Frame <u>do</u>	Masts, Yards, &c. <u>Complete & Good</u>
Lower Deck Beams & Fastenings <u>Sound</u>	Keelsons <u>do</u>	Sails <u>do</u> <u>do</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>3 1/2</u> <u>1 Stem Wedge</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>Complete & Good</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u> <u>do</u>
Wales <u>do</u>	Copper <u>Yellow Metal</u> When put on <u>Feb 1861</u>	Standing & Running Rigging <u>do</u> <u>do</u>
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good

Is now in good efficient Condition fit for the safe Conveyance of
Dry and Perishable Cargoes to and from all parts of the World and
to continue as afloat

The Amount of Fee.....£ 2 : 0 : 0 is received by me,

Special..... 2 : 2 : 0

Certificate (if required) : : :

Committee's Minute 5th March 1861

Character assigned GA 1

record damage repair



© 2019

Lloyd's Register
Foundation

GLS 142 - 0434