

1908

REPORT of SURVEY for REPAIRS.

Rec 27/5/62

No. 1908 Survey held at Glasgow Date 17th May 1862
on the Ship "Robert Henderson" Master P. Logan
Tonnage 552 Built at Aberdeen When built 1857
By whom built _____ Owners Henderson
Port belonging to Glasgow Destined Voyage New Zealand
If Surveyed Afloat or in Dry Dock Patent Slip Barclay Curle & Co.

Last Survey, No. 1812 Port Glasgow Classed g 6.61

REPAIRS At Present, Stripped the Yellow Metal Sheathing, Caulked from Keel upwards to two beams on Deck and Resheathed the Bottom with Yellow Metal on Felt to 16 feet Water Line
Windlass Unhung and Stripped and found quite sound

Present Condition of the

Decks <u>Good</u>	Treenails <u>Where Seen, Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>Where Seen do</u>	Breasthooks and Stemson <u>Not Seen</u>	Pumps <u>Complete & Good</u>
Comings <u>Good</u>	Transoms, Pointers, and Crutches <u>Where Seen do</u>	Boats <u>do do</u>
Upper Deck Beams & Fastenings <u>Where Seen do</u>	Timbers of the Frame <u>do</u>	Masts, Yards, &c. <u>do do</u>
Lower Deck Beams & Fastenings <u>Good</u>	Keelsons <u>do</u>	Sails <u>do do</u>
Planksheers <u>do</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>do do</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>do do</u>
Topsides <u>do</u>	Rudder <u>Complete & Good</u>	Hawsers and Warps <u>do do</u>
Wales <u>do</u>	Copper <u>Yellow Metal on Felt</u>	Standing & Running Rigging <u>do do</u>
Plank (Bottom) and Counter <u>do</u>	When put on <u>1862</u>	

General Observations and Opinion, Eligible to remain as Classed
Caulking of Bottom, Deck, & Waterways. Good


The Amount of Fee.....£ 4 : 4 : is received by me,

Special Caulking 2 : 2 :

Certificate (if required) : : :

Committee's Minute 30th May 1862.

Character assigned g Record Yell



© 2019
Lloyd's Register
Foundation