

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No. 2214** Survey held at Glasgow Date 22nd July 1864
 on the Ship Robert Henderson Master P. Logan
 Tonnage 552 Built at Aberdeen When built 1854
 By whom built _____ Owners P. Henderson & Co
 Port belonging to Glasgow Destined Voyage New Zealand
 If Surveyed Afloat or in Dry Dock Ed. Mc Gregor Dry Dock

Last Survey, No. 1908 Port Glasgow Classed G.A. 1.
 62

REPAIRS Yellow Metal Sheathing Stripped, Bottom Rubbed Bright, Reanched from Keel over all and Reheathed with Yellow Metal on Selt to the Upper part of keels

Present Condition of the

| | | |
|---|--|---|
| Decks <u>Where Seen Good</u> | Treenails <u>Where Seen Good</u> | Windlass and Capstan <u>Good</u> |
| Waterways <u>do</u> | Breasthooks and Stemson <u>do</u> | Pumps <u>do</u> |
| Comings <u>do</u> | Transoms, Pointers, and Crutches <u>do</u> | Boats <u>do</u> |
| Upper Deck Beams & Fastenings <u>do</u> | Timbers of the Frame at the openings <u>do</u> | Masts, Yards, &c. <u>do</u> |
| Lower Deck Beams & Fastenings <u>do</u> | Ditto Ditto at other places <u>do</u> | Sails <u>do</u> |
| Planksheers <u>do</u> | Keelsons <u>Where Seen Good</u> | Anchors No. of <u>313 1/2</u> <u>Stem Merge</u> |
| Sheerstrakes <u>do</u> | Clamps and Shelves <u>do</u> | Cables <u>Good</u> |
| Topsides <u>do</u> | Ceiling <u>do</u> | Hawsers and Warps <u>do</u> |
| Wales <u>do</u> | Rudder <u>do</u> | Standing & Running Rigging <u>do</u> |
| Plank (Bottom) and Counter <u>do</u> | Copper <u>Plated</u> When put on <u>1864</u> | |

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

Appears in good Condition, Eligible in my opinion to remain as Classed

The Amount of Fee.....£ : : is received by me,

Special..... / : / :

Certificate (if required) : : :

Committee's Minute 5th August 1864

Character assigned G.A. 1
second 4M

J. Darling