

REPORT of SURVEY for REPAIRS.

Recd 20/10/64

No. in Reg. Book. **No. 2252** Survey held at Bowling Bay Date 15th October 1864
 524 on the Schoner Progress Master Donald Campbell
 Tonnage 60 Built at Rothesay When built 1861
 By whom built Mc Lean Owners J. Campbell
 Port belonging to Greenock Destined Voyage Coaster
 If Surveyed Afloat or in Dry Dock Scott & Macgill's Patent Slip

Last Survey, No. 4312 Port Greenock Classed A.S.
61

REPAIRS Windlass Stopped, Examined and Relined, New Rider Nelson of German Oak 6x12 in and Four Pairs of Knee Pieces added, Reel Recaulked from Nail to Gunwale

Present Condition of the

Decks <u>Where Seen Good</u>	Treenails <u>Where Seen Good</u>	Windlass and Copstan <u>Winch Good</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame at the openings <u>do</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Ditto Ditto at other places <u>do</u>	Sails <u>do</u>
Planksheers <u>Where Seen Good</u>	Keelsons <u>do</u>	Anchors No. of <u>2 Bk 1 Star 1 Midge</u>
Sheerstrakes <u>do</u>	Clamps and Shelves <u>do</u>	Cables <u>Complete</u>
Topsides <u>do</u>	Ceiling <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Rudder <u>do</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>do</u>	Copper <u>Single</u> When put on <u>Bottom</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

Appears in good Condition Eligible in my opinion to remain as Classed


The Amount of Fee.....£ : : is received by me,

Special..... : 10 : 6

Certificate (if required) : : :

Committee's Minute 21st October 1864

Character assigned 721



© 2019

Lloyd's Register Foundation