

REPORT of SURVEY for REPAIRS.

2681

Rev 24/8/67

No. in Reg. Book. **No. 2681** Survey held at **Glasgow** Date **23rd August** 18**67**
 on the **Ship "Caledonia"** Master **Mr. Lean**
 Tonnage **383** Built at **Glasgow** When built **1841**
 By whom built **438** Owners **James & Alex Allan**
 Port belonging to **Glasgow** Destined Voyage **Monte Video**
 If Surveyed Afloat or in Dry Dock **Alexander Stephen & Sons Patent Ship**

Last Survey No. **2436** Port **Glasgow** Classed **10 A \ Red**
 REPAIRS **Yellow Metal Sheathing Patched and Nailed where required**
 Rep 55-743 C2 66 55.66-743

Present Condition of the

Decks White Lead Good	Treenails White Lead Good	Windlass and Capstan Good
Waterways do	Breasthooks and Stemson do	Pumps do
Comings do	Transoms, Pointers, and Crutches do	Boats do
Upper Deck Beams & Fastenings do	Timbers of the Frame at the openings do	Masts, Yards, &c. do
Lower Deck Beams & Fastenings do	Ditto Ditto at other places do	Condition, how ascertained from Examination
Planksheers do	Keelsons do	Sails Complete
Sheerstrakes do	Clamps and Shelves do	Anchors No. of 3 1/2 1 Stem 2 Mice
Topsides do	Ceiling do	Cables Complete
Wales do	Rudder do	Hawsers and Warps do
Plank (Bottom) and Counter do	Copper Yellow Metal When put on 1866	Standing & Running Rigging do

General Observations and Opinion,

is in good condition, Eligible in my opinion to remain as classed
 Caulking of Bottom, Deck, & Waterways. **Good where tested**

The Amount of Fee.....£ : : is received by me,

Special..... / : / :

Certificate (if required) : : :

Committee's Minute **27 August** 18**67**

Character assigned **Red** **M.S.**

D. R. Darling



© 2019
 Lloyd's Register
 Foundation
 GLS144-0056