

3201

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. 269 No. 3201 Survey held at Glasgow Date Augst 9th 1870
on the Ship Robert Henderson Master McDonald
Tonnage 552 built at Aberdeen When built 1857
By whom built _____ Owners Albion Shipping Coy
Port belonging to Glasgow Destined Voyage New Zealand
If Surveyed Afloat or in Dry Dock God's Ship

Last Survey, No. 30208 Port Gt. London Classed A.I.
REPAIRS now done. font 66-67

The bottom sighted and the yellow metal sheathing patched - new Bowsprit and main yard of Pine -

Present Condition of the

| | | | | | |
|-----------------------------------|---------|--|----------------------------|---|--------------|
| Decks | } good | Treenails | good | Windlass and Capstan | } good |
| Waterways | | Breasthooks and Stemson | | Pumps | |
| Comings | | Transoms, Pointers, and Crutches | where | Boats | |
| Upper Deck Beams & Fastenings | | Timbers of the Frame at the openings | | Masts, Yards, &c. | |
| Lower Deck Beams & Fastenings | } where | Ditto Ditto at other places | seen | Condition, how ascertained <u>from the deck and</u> | |
| Planksheers | | Keelsons | | Sails | |
| Sheerstrakes | | Clamps and Shelves | hold | Anchors No. of <u>3/15 20</u> | |
| Topsides | | Ceiling | much lumbered | Cables | |
| Wales | } seen | Rudder | | Hawsers and Warps | } sufficient |
| Plank (Bottom) and Counter | | When put on <u>1869</u> | Standing & Running Rigging | | |
| General Observations and Opinion, | | Caulking of Bottom, Deck, & Waterways. | good where seen | | |

She is now where seen in good and efficient condition, and fit in my opinion to remain as

The Amount of Fee.....£ : : : is received by me,

Special..... / : / : :

Certificate (if required) : : : :

Committee's Minute 13th September 1870

Character assigned font 66-67

Classed A.I.

J. Hornish

J.P.M.



© 2019

Lloyd's Register Foundation