

# REPORT of SURVEY for REPAIRS.

Rev 24/11/90

No. in Reg. Book. **No. 3232** Survey held at Glasgow Date 5<sup>th</sup> to 9<sup>th</sup> Nov 1870  
on the S<sup>4</sup> Berbice Master D. Latta  
Tonnage 717 built at Dumharton When built 1860  
By whom built M<sup>r</sup> Millan Owners J. Kerr  
Port belonging to Greenock Destined Voyage Clas to Bombay  
If Surveyed Afloat or in Dry Dock Refr. Barclay, Currie & Co. Shipway

Last Survey, No. 2864 Port Greenock Classed 14 A 1  
REPAIRS 9. 60

The yellow metal sheathing stripped off, two of the screw bolt bolts driven out, which with the surrounding parts were found good. The bottom caulked and resheathed with yellow metal over part felt.

## Present Condition of the

Decks	Good	Freenails/Bills	Good	Windlass and Capstan	Good
Waterways		Breasthooks and Stemson			
Comings		Transoms, Pointers, and Crutches			
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings			
Lower Deck Beams & Fastenings	None	Ditto Ditto at other places	None	Condition, how ascertained	Suff
Planksheers		Keelsons			
Sheerstrakes		Clamps and Shelves			
Topsides		Ceiling			
Wales	Seen	Rudder gear refitted.	Seen	Sails	None
Plank (Bottom) and Counter		Copper <u>seen</u> When put on <u>11. 70</u>		Anchors No. of	
		Caulking of Bottom, Deck, & Waterways.	Good when examined	Cables	Seen
				Hawsers and Warps	Seen
				Standing & Running Rigging	Seen

General Observations and Opinion,

This ship appears in good and efficient condition eligible to remain as classed 14 A 1

The Amount of Fee.....£ " : " : is received by me,

Special..... 1 : 1 : "

Certificate (if required) " : " : "

Committee's Minute 25<sup>th</sup> Nov 1870

Character assigned 14 A 1

record W. H.



© 2019

Lloyd's Register Foundation

GLS 144-0333