

REPORT of SURVEY for REPAIRS, &c.

4083

(Rev. 16/8/75)

No. in Reg. Book. **No. 4083** Survey held at **Glasgow** Date, first Survey **and** Last Survey **6th August 1875**

on the **Bk Falcon** Master **W Guirer**
 TONNAGE under Tonnage Deck **375** Built at **Plymouth** When built **1865** YEAR. MONTH.
 Ditto of Span Deck, or Attoning Deck **20** Owners **Foulds & Bona** Port belonging to **London**
 Ditto of ~~Beam~~ Raised Qr. Dk. **20** Residence **Greenock**
 Ditto of ~~Beam~~ Forecastle **395** By whom built **Manne** Destined Voyage **Demerara**
 Gross Tonnage **395** If Surveyed Afloat or in Dry Dock **Afloat**
 Crew Space, as per Rule **395**
 Register Tonnage, cut on Beam **395**
 Engine Room
 Reg. Tonnage as ~~Beam~~, cut on Beam

Length of ~~Beam~~ ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck **25 1/2** ft. Years assigned. Character in Register Book.
 Last Survey, No. **34438** Port **London** Classed **13 A1**
HT Sgd. 72.
Lon 2.75

REPAIRS, OR EXAMINATION AS PER RULE

Notice was called to this vessel having been resheathed with yellow metal, when it was found that she had been docked, stripped, not caulked but remetalled in fact in Messrs McMillan's dock at Dumbarton at the commencement of the recent fair holidays no notice having been given at that time that she was about to be, or in dock. her loading was at the date of this visit nearly completed.

Cause of Repairs to be clearly stated.

Present Condition of the			
Decks	Good	Treenails	Not seen
Waterways		Breasthooks and Stemson	
Comings		Transoms, Pointers, and Crutches	
Upper Deck Beams & Fastenings	Not seen	Timbers of the Frame at the openings	
Lower Deck Beams & Fastenings		Ditto Ditto at other places	
Planksheers	Good	Keelsons	
Sheerstrakes		Clamps and Shelves	
Topsides		Ceiling	
Wales		Rudder	Good
Plank (Bottom) and Counter	Not seen	Copper Good When put on 7.75	
Engine Room Skylights		Caulking of	
General Observations, Opinion as to Class, &c.		Bottom, Deck, & Waterways	Good as far as seen
		Scuppers	Good
		Cargo and Main Hatchways	Good
		Hatches	Good

As far as now seen she appears in good and efficient condition and as she was surveyed in London in February last I beg to suggest that she should remain as classed upon that date of survey being the remetalting in fact.

The Amount of Entry Fee ... £ 4 : 0 : 0 received by me, **15th Aug 1875**
 Special ... £ 1 : 1 : 0
 Certificate (if required) ... £ : : :
 (Travelling Expenses, if any, £ 1 : 1 : 0)
 Committee's Minute **17th August 1875**

W. J. Thompson
 Surveyor to Lloyd's Register of British and Foreign Shipping.

Character assigned **Revised Y May 5 13**
2.75
17/1/75
GL 5145-0076

