

Report of Survey for Repairs of Engines and Boilers.

No. 5313

(Received at London Office, 7/3/81)

No. in Reg. Book. Survey held at

Glasgow

Date, first Survey Sept 22nd Last Survey Sept 25th 1881125th on the Machinery of the

S. S. "Corcyra"

(Number of Visits 3)

Tonnage, Gross 779

Built at Stockton

When built 1862

Ditto, Net 494

Owners Palgrave Murphy & Co

Port belonging to Dublin

Diameter of Cylinders 26" + 49"

Engines made by Richardson, Hartlepool

When made 1876

Length of Stroke 30"

Boilers made by

When made 1876

Pressure of Steam 65 lbs

If Surveyed Afloat or in Dry Dock Both

Classed

Years assigned. Character in Register Book.

Registered Horse Power 99

Last Survey No. 26308

Port Inver

Lloyds M.C. 3.80

Particulars of Repairs and Examination Cylinders opened up & Pistons examined
 Crank & Lunnel Shafting examined pumps, pipes & hoses examined
 Sea cocks & valves ground & overhauled. Propeller examined

Boiler, thoroughly examined and several new screw stays
 fitted in back of Combustion Chambers, Tubes (upper rows) also
 stays & Furnace bottoms. Somewhat pitted & corroded, but very little
 worse than when examined in March 1880 (See Glasgow Report 504th)
 otherwise the Boiler is in good condition.

General Observations, Opinion, and Recommendation: The Engines & Boilers are now

in good order & safe working condition and eligible in my opinion

to be noted in the Register Book Lloyds M.C. 3.81 subject to

the Boiler being again submitted for examination in twelve months

by one of the Society's Surveyors, owing to the corrosion of the parts above referred to.

Entry or Registering Fee ... £ " : " : "

Survey Fee ... £ 2 : 2 : " received by me, }

Certificate (if required) ... £ " : " : " 4th March 1881 }

Travelling Expenses, if any, £

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

Tuesday March, 5th 1881.

Assigned

Lloyd's Owners 11/3/81

Lloyds M.C. 3.81

subject to further survey of Boilers in 12 months

Clyde District

Lloyd's Register Foundation

or to be clearly stated.

(Insert Character precisely as in the Register Book.)

5313.920.

The machinery of the vessel has been examined
and is reported to be in good condition, except
so far as the Boiler is concerned which
is badly corroded. Submitted that she
is eligible to have Lloyd's M.C. 3.81
provided the Boiler is again
examined in twelve months
time from this date,

DTWMM
7.3.81



© 2019

Lloyd's Register
Foundation