

Report of Survey for Repairs of Engines and Boilers.

No. 5373 (Received at London Office, 11/5/81)

No. in Reg. Book. 245 Survey held at Glasgow Date, first Survey 28th April Last Survey 2nd May 1881

on the Machinery of the S.S. Carfin (Number of Visits 2)

Tonnage, Gross 1190 Built at Glasgow When built 1877

Ditto, Net 766 Owners M^r Dixon (Lim) Port belonging to Glasgow

Diameter of Cylinder 31" x 54" Engines made by London & Glasgow (Lim) When made 1877

Length of Stroke 36 Boilers made by London & Glasgow (Lim) When made 1877

Pressure of Steam 70 lbs If Surveyed Afloat or in Dry Dock both Classed 100 A1

Registered Horse Power 150 Character in Register Book. 11-80

Last Survey No. Ships M.C. 2-80

Particulars of Repairs and Examination for S.S. No. 1.

Sea cocks examined & found in good condition

Tail shaft drawn examined & found in good condition

A new screw propeller fitted.

Cylinder examined & valves & found in good condition,

Crank shaft examined & found in good condition

Main Bolt examined & found in good condition.

Pump, pipe, hoses & connections examined & found in good condition.

General Observations, Opinion, and Recommendation:— The Engines and Boilers are now in good order & safe working condition & eligible in my opinion to be noted in the Register Book, Ships M.C. 4-80

Entry or Registering Fee ... £ 3 : 3 : 0

Survey Fee ... £ 7 : 5 : 0 received by me, [Signature]

Certificate (if required) ... £ 7/5/1881

(Travelling Expenses, if any, £ — : — : —)

Committee's Minute Tuesday, May, 10th 1881.

Assigned [Signature]

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Glasgow

Lloyd's Register Foundation

GLS145-0402

5373 c/s

It is submitted that this
vessel is eligible to have
the notification

Lloyd's No. 5-87

Recorded

PM

9/5/87



© 2019

Lloyd's Register
Foundation