

REPORT of SURVEY for REPAIRS, &c.

(Received at London Office, 22nd JUNE 82.)

No. 5742

No. in Survey held at Reg. Book.

Glasgow

Date, first Survey 20 May

Last Survey 3rd June

1882

Master R. Walker

YEAR.

MONTH.

TONNAGE under Tonnage Deck  
Ditto of Spar Deck, or Avoning Deck  
Ditto of Poop  
Ditto of Raised Qr. Dk.  
Ditto of Houses on Deck  
Ditto of Forecastle  
Gross Tonnage  
Crew Space, as per Rule  
Register Tonnage, net on Beam  
Engine Room  
Reg. Tons as St' mer, cut on Bm.

Built at Belfast

When built 1881

Owners A. C. Colvill

Port belonging to Glasgow

Residence Glasgow

By whom built Workman & Clark Destined Voyage Bilbao

If Surveyed Afloat or in Dry Dock Henderson's slip & afloat  
(State Name of Dock)

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft. Years assigned. Character in Register Book.

Last Survey, No. 2743 Port Bel

REPAIRS, OR EXAMINATION AS PER RULE Annual Survey

Cause of Repairs to be clearly stated.

The bottom of the vessel cleaned and recoated.  
The starboard chain cable ranged (including 30 fathoms new) 120 fathoms. Certificate of test for the 30 fms 1 1/8 chain No. 10580 dated Netherston 23 Feb'y 1882, sigd. D. G. Lewis. Tests 5 c 2 L. 22-15-0-0 and 34-2-2-0.  
Also a bower anchor supplied new, weighten stock 10-0-19. Test 5 c 2 L. 12-4-1-14. certificate of test (duplicate) No. 9260, dated Netherston 6 April 1880, signed D. G. Lewis.

Present Condition of the

Decks	good	Treenails	Rivets	good	Windlass and Capstan	good
Waterways	"	Breasthooks and Stems	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Scutches	"	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	"	Condition, how ascertained	from deck
Planksheers	"	Keelsons	"	"	Sails	good
Sheerstrakes	"	Clamps and Shelves	"	"	Anchors No. of	3 B. 1 B. 2 H.
Topsides	Plating	Ceiling	"	"	Cables port chain said to be complete	
Wales	"	Rudder	"	"	Starboard chain ranged 120 fms.	
Plank (Bottom) and Counter	"	Copper (or Y.M.)	When put on	"	Hawsers and Warps	good and
Engine Room Skylights	good	Caulking of	"	"	Standing & Running Rigging	sufficient
Coal Bunker, Openings, Lids, &c.	good	Bottom, Deck, & Waterways	good	"	Cargo and Main Hatchways	good
General Observations, Opinion as to Class, &c.		Scuppers	good	"	Hatches	good

This vessel is now in good and efficient condition and is eligible in my opinion to remain as classed.

The Amount of Entry Fee ... £ : : received by me, 20/6/1882

Special ... £ 1 : 1 : 0

Certificate (if required) to be sent as per margin... £ : :

(Travelling Expenses, if any, £ )

Committee's Minute

Friday, 23rd June, 1882.

Character assigned

100A.1.

G. Stanbury  
Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation

GLS146-0442



REPORT of SURVEY for REPAIRS, &c.

(Received at London Office, 22nd JUNE 82.)

No. 5742

No. in Survey held at  
Reg. Book.

Glasgow

Date, first Survey 20 May

Last Survey 3rd June

1882

Master R. Walker

YEAR.

MONTH.

TONNAGE under Tonnage Deck  
Ditto of Spar Deck, or Avoning Deck  
Ditto of Poop  
Ditto of Raised Qr. Dk.  
Ditto of Houses on Deck  
Ditto of Forecastle  
Gross Tonnage  
Crew Space, as per Rule  
Register Tonnage, net on Beam  
Engine Room  
Reg. Tons as St' mer, cut on Bm.

Built at Belfast

When built 1881

Owners A. C. Colvill

Port belonging to Glasgow

Residence Glasgow

By whom built Workman & Clark

Destined Voyage Bilbao

If Surveyed Afloat or in Dry Dock Henderson's slip & afloat

(State Name of Dock)

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft. Years assigned. Character in Register Book.

Last Survey, No. 2743

Port Bel

Classed 100A.1.

REPAIRS, OR EXAMINATION AS PER RULE

Annual Survey

Cause of Repairs to be clearly stated.

The bottom of the vessel cleaned and recoated.  
The starboard chain cable ranged (including 30 fathoms new) 120 fathoms. Certificate of test for the 30 fms 1 1/8 chain No. 10580, dated Netherthorn, 23 Feb'y 1882, sig'd. D. G. Lewis. Tests 5 c 2 L. 22-15-0-0 and 34-2-2-0.  
Also a lower anchor supplied new, weighten stock 10-0-19. Test 5 c 2 L. 12-4-1-14. Certificate of test (duplicate) No. 9260, dated Netherthorn 6 April 1880, signed D. G. Lewis.

Present Condition of the

Decks	good	Treenails	Keels	good	Windlass and Capstan	good
Waterways	"	Breasthooks and Stems	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Scutches	"	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	"	Condition, how ascertained	from deck
Planksheers	"	Keelsons	"	"	Sails	good
Sheerstrakes	"	Clamps and Shelves	"	"	Anchors No. of	3 B. 1 B. 2 H.
Topsides	Plating	Ceiling	"	"	Cables port chain said to be complete	
Wales	"	Rudder	"	"	Starboard chain ranged 120 fms.	
Plank (Bottom) and Counter	"	Copper (or Y.M.)	When put on	"	Hawsers and Warps	good and
Engine Room Skylights	good	Caulking of	"	"	Standing & Running Rigging	sufficient
Coal Bunker, Openings, Lids, &c.	good	Bottom, Deck, & Waterways	good	"	Cargo and Main Hatchways	good
General Observations, Opinion as to Class, &c.		Scuppers	good	"	Hatches	good

This vessel is now in good and efficient condition and is eligible in my opinion to remain as classed.

The Amount of Entry Fee ... £

received by me,

Special ... £

20/6/1882

Certificate (if required)

to be sent as per margin...

(Travelling Expenses, if any, £)

Committee's Minute


Friday, 23rd June, 1882.

Character assigned

100A.1

G. Stanbury

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation

GLS146-0442