

# REPORT of SURVEY for REPAIRS, &c.

No. 5892

No. in Survey held at Reg. Book.

394 on the

Glasgow

Date, first Survey 2<sup>d</sup> Nov

Last Survey 2<sup>d</sup> Nov

1882

(No. of Visits)

Master J. L. Johnson

TONNAGE under Tonnage Deck

798

Ditto of Spar Deck, or Awning Deck

Ditto of Poop

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage

863

Crew Space, as per Rule

Register Tonnage, cut on Beam

Engine Room

Reg. Tons as Stmer, cut on Bm.

837

Built at

Sunderland

When built

1864

Owners

J. L. Johnson

Port belonging to

Xianyu from Glasgow

Residence

By whom built

Smurthwaite

Destined Voyage Not Fixed

Surveyed Afloat or in Dry Dock in Queen Dock

(State Name of Dock)

Length of Poop

ft. Ditto, Forecastle

ft. Ditto, Raised Quarter Deck

ft.

Years assigned.

Character in Register Book.

Last Survey, No. 5791

Port Port. Gls

Classed 14 A1

REPAIRS, OR EXAMINATION AS PER RULE

Cause of Repairs to be clearly stated.

78

9

11.79

Examination of Bower Anchor to complete equipment

Now Supplied. 1 Bower Anchor, Weight 25.3.0 of Stock  
Test as per Certificate 25.8.0.14, tested at Sipton, 28<sup>th</sup> Oct 1882.  
E. R. Lutt, Supt.

This Anchor has now been supplied to complete equipment, being found deficient at last Survey the particulars of same are recorded in Glasgow Report No 5791, dated 25<sup>th</sup> July 1882 & Owners letter attached thereto.

Present Condition of the

ks

Word

Greenails

When seen

Word

Windlass and Capstan

Word

ways

"

Breasthooks and Stemson

"

Pumps

"

rs

"

Transoms, Pointers, and Crutches

"

Boats 4

"

Deck Beams & Fastenings

"

Timbers of the Frame at the openings

"

Masts, Yards, &c.

"

er Deck Beams & Fastenings

"

Ditto Ditto at other places

"

Condition, how ascertained On Deck

anksheers

"

Keelsons Not seen amidships

"

Sails Sufficient

strakes

"

Clamps and Shelves

"

Anchors No. of 3B. 15. 2 R

des

"

Ceiling

"

Cables Said to be complete

Wales

"

Rudder

"

Hawsers and Warps Sufficient

Plank (Bottom) and Counter

✓

Caulking of

Bottom, Deck, & Waterways

Good when seen

Standing & Running Rigging

Engine Room Skylights

✓

Coal Bunker, Openings, Lids, &c.

✓

Scuppers

Good

Cargo and Main Hatchways

Good

Hatches

General Observations, Opinion as to Class, &c.

The Bower Anchor having now been supplied & the vessel otherwise appearing in good condition, I am of opinion she is eligible to remain as classed.

The Amount of Entry Fee ... £ 0 : 0 : 0

received by me,

Special ... £ : : 188

Certificate (if required)

to be sent as per margin... £ 0 : 5 : 0

(Travelling Expenses, if any, £ )

Committee's Minute

Tuesday, 7<sup>th</sup> November, 1882

Character assigned

Good 9 A1

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register

Foundation