

Report of Survey for Repairs of Engines and Boilers.

5912

No. 5912

(Received at London Office, 27th Nov. 82.)

No. in Survey held at

Glasgow

Date, first Survey

20th Nov

Last Survey

20th Nov 1882

on the Machinery of the

Steamer *Glan Monroe*

(Number of Visits One)

Tonnage, Gross

2197

Built at

Sunderland

When built

1881

Ditto, Net

1437

Owners

Messrs Gairner Irvine & Co

Port belonging to

Glasgow

Diameter of Cylinder

36 & 68"

Engines made by

Messrs R & W Hawthorn

When made

1881

Length of Stroke

45"

Boilers made by

Do

When made

1881

Pressure of Steam

90 lbs

If Surveyed Afloat or in Dry Dock

Govan Dry dock

Classed

Character in Register Book.

Registered Horse Power

300

(State name of Dock.)

Years assigned.

100 A1

5-82

Last Survey No.

Port

"LLOYD'S M.C." 12-81

Particulars of Repairs and Examination

(State cause of Repairs.)

Examined the connections of valves, cocks &c. to plating of vessel while in dock - The Propeller & nut were also examined - One new blade fitted which appeared to be done satisfactorily -

General Observations, Opinion, and Recommendation:— While this vessel was in Dry dock the condition of the sea cocks, valves, propeller &c was ascertained to be good & I would recommend that the machinery remain as classed in the Register Book.

Entry or Registering Fee... £ 0 : 0 : 0

Survey Fee (per Section 28) ... £ 0 : 0 : 0

Certificate (if required) ... £ : : 188

(Travelling Expenses, if any, £)

Committee's Minute

188

Assigned

Walter E. Robson

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Glasgow

Lloyd's Register Foundation

GLS 147-0202

5912 gls

Submitted that this vessel is
eligible to remain as blessed

D. J.

27/11/82



© 2019

Lloyd's Register
Foundation