

ANNUAL SURVEYS.

(Received at London Office, 15th FEB. 83.)

No. 6005 Survey held at Glasgow Date, first Survey 8th Jan'y Last Survey 12th Feb'y 1883
 No. in Reg. Book. 750 on the Ship City of Florence Master Leach
 Net 1200 Built at Glasgow When built 1867
 Tonnage Gross 1200 Under Dk. 1162 By whom built W. & J. Smith & Sons Owners G. Smith & Sons
 Port belonging to Glasgow Destined Voyage San Francisco
 If Surveyed Afloat or in Dry Dock Govan dry dock & afloat in Queens Dock
 (State Name of Dock.)

Last Survey, No. 28277 Port of Glasgow Classed SS Lower 3-80 11.80
 Present Condition of the Decks good Planks good
 Waterways 4 Breasthooks and Stems 4
 Comings 4 Transoms, Pointers, and Crutches 4
 Upper Deck Beams & Fastenings 4 Timbers of the Frame at the Openings 4
 Lower Deck Beams & Fastenings 4 Ditto ditto at other places 4
 Planksheers 4 Keelsons 4
 Sheerstrakes 4 Clamps and Shells 4
 Topsides 4 Ceiling 4
 Wales 4 Rudder 4
 Plank (Bottom) and Counter 4 Copper or V.M. When put on 4
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good

General Observations, Opinion as to Class, &c.
Now done The bottom cleaned and painted. New main topmast fitted. Is now in good condition and eligible in our opinion to remain as classed *A 1

Committee's Minute Friday, 16th February, 1883.
 Character assigned T.W. *A 1
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. 6005 Survey held at Glasgow Date, first Survey 29th Jan'y Last Survey 30th Jan'y 1883
 No. in Reg. Book. 366 on the Ship "Scottish Wizard" Master G. Scale
 Net 1140 Built at Aberdeen When built 1881
 Tonnage Gross 1209 Under Dk. 1044 By whom built A. Hall & Co. Owners McKerran & McEacharn
 Port belonging to London Destined Voyage Queensland
 If Surveyed Afloat or in Dry Dock Govan dry dock
 (State Name of Dock.)

Last Survey, No. 3873 Port of Abn Classed 100 A 1 9.81
 Present Condition of the Decks good Planks good
 Waterways 4 Breasthooks and Stems 4
 Comings 4 Transoms, Pointers, and Crutches 4
 Upper Deck Beams & Fastenings 4 Timbers of the Frame at the Openings 4
 Lower Deck Beams & Fastenings 4 Ditto ditto at other places 4
 Planksheers 4 Keelsons 4
 Sheerstrakes 4 Clamps and Shells 4
 Topsides 4 Ceiling 4
 Wales 4 Rudder 4
 Plank (Bottom) and Counter good Copper or V.M. When put on 4
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good

General Observations, Opinion as to Class, &c.
Now done The bottom cleaned and painted. Is now in good condition & eligible in our opinion to remain as classed 100 A 1

Committee's Minute Friday, 16th February, 1883.
 Character assigned T.W. 100 A 1
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

(If a Steam Ship, state if a Report is also sent on the Machinery)

(The Surveyors are requested not to write on or below the space for Committee's Minute)

(Form No. 3 for Annual Survey, when there are no repairs. The Surveyors are requested not to write on or below the space for Committee's Minute)

(Insert Character precisely as in Register Book.)

(Insert Character precisely as in Register Book.)

© 2019 Lloyd's Register Foundation
 GLS147-0326